

**PRIORITY**

OUT55376

P 020129Z  
 FM NPIC WASHDC  
 TO RUCSC/SAC OFFUTT AFB OMAHA NEB  
 RUCVAA/4080 STRAT WG OL 19 BARKSDALE AFB LA  
 RUCVAA/2D RTS BARKSDALE AFB LA  
 RUEKDA/DIA WASHDC  
 RUECYH/NAVRECONTECHSUPPCEN SUITLAND MO  
 RUEPIA/CIA WASHDC  
 RUWBKN/15TH AF MARCH AFB RIVERSIDE CALIF  
 RUWGAA/2AF BARKSDALE AFB LA  
 BT  
 S E C R E T CITE NPIC 4179.

1965 APR 2 01 47Z

15TH AF (FOR DI), SAC (FOR DIM/GOLDEN TREE/DOCR, DM 4) 2D AF (FOR DI) 2 APR 1965

1. CAMERA B 122 WAS USED IN MISSION 3997 FLOWN ON 31 MARCH 1965  
 PROCESSING WAS ACCOMPLISHED BY NAV RECON TECH SUPPCEN.

## 2. ORIGINAL NEGATIVE:

A. THE EXPOSURE WAS ADEQUATE, AND THE RESOLUTION IS GOOD.

B. 9R SIDE: A SCRATCH LOCATED WITHIN 0.2" TO 0.3" FROM THE  
 TITLED EDGE OF THE FILM IS CONTINUOUS THROUGHOUT THE FIRST 200  
 FRAMES. A WAVY PLUS DENSITY STREAK ABOUT 1.0" FROM THE INBOARD  
 EDGE APPEARS INTERMITTENTLY THROUGHOUT THE MISSION LASTING FOR  
 SEVERAL FRAMES AT A TIME. ANOTHER PLUS DENSITY STREAK 3.0" FROM  
 THE INBOARD EDGE RUNS CONTINUOUSLY THROUGH FRAMES 170 TO 1200.  
 MINUS DENSITY DOTS, SPACED 1.55" APART EXIST 1.5" AND 5.2" FROM  
 THE OUTBOARD EDGE THROUGHOUT THE MISSION. ABRASIONS, SCRATCHES,  
 AND EMULSION LIFTS ARE PRESENT IN FRAME 1576. DIAGONAL CREASES  
 OCCURRED IN FRAMES 1267, 1374 TO 1375, 1512 TO 1514, AND 2803  
 TO 2804. FINE PLUS DENSITY LINES PARALLEL TO THE MAJOR AXIS OF THE  
 FILM ARE PRESENT THROUGHOUT PART 2. MANUFACTURING SPLICES EXIST  
 IN FRAME 498 WITH ASSOCIATED STATIC FOG ON 500 AND IN FRAME 2085

COPIES RECEIVED		
CyNo.	Office	Act.
	Master File	
	OS	
	ADMIN	
	SEC BR	
	P&DS	
	CSD	
	IPD	
	PD	
	PSD	
3,4	TID	
	PAG	
	CIA/PID	
	DIAX-4	
	SPAD	
	NSA LO	
	DIAAP	
	Destroyed	

**SECRET**

GROUP 1  
 Excluded from automatic  
 downgrading and  
 declassification

-2-

WITH ASSOCIATED STATIC ON 2087. SEVEN HEAT SPLICES WERE MADE BETWEEN ADJACENT FRAMES ON THIS SIDE OF THE MISSION. TWO ADDITIONAL HEAT SPLICES WERE MADE IN THE FORMAT OF FRAMES 313 AND 1577. THE LATER SPLICE HAS AN ASSOCIATED TEAR ADJACENT TO IT AND HAS BEEN REPAIRED WITH MYLAR TAPE.

C. 9L SIDE: PLUS DENSITY STREAKS ARE INTERMITTENT THROUGHOUT THIS SIDE OF THE MISSION. THE EDGES OF THE FILM ARE SCALLOPED FROM FRAME 949 TO 960. THIS WAS CAUSED BY THE FILM NOT TRACKING PROPERLY IN THE LACQUERING MACHINE. THERE IS A MANUFACTURING SPLICE IN FRAME 2745. TEN HEAT SPLICES APPEAR BETWEEN ADJACENT FRAMES ON THIS SIDE. TWO ADDITIONAL HEAT SPLICES OCCUR WITHIN THE FORMAT OF FRAMES 306 AND 1610.

D. BOTH SIDES: THE DATA CLOCK FRAME COUNTER STOPPED AT 300 (TITLED FRAME 299). IT WAS INOPERATIVE THROUGHOUT THE REMAINDER OF THE MISSION. EVIDENCE OF INBOARD AND OUTBOARD EDGE STATIC IS PRESENT ON ALL FRAMES IN THE MISSION. THERE ARE 2824 TITLED FRAMES ON EACH SIDE OF THE MISSION.

E. THERE WERE NO MAJOR CAMERA OR PROCESSING MALFUNCTIONS IN THE MISSION.

3. POSITIVE:

A. THE PI SUITABILITY IS GOOD.

B. THE PRINTING AND PROCESSING WAS GOOD.

C. CLOUDS DEGRADE APPROXIMATELY 15 PERCENT OF THE MISSION

IMAGERY. GP-1

S E C R E T

--END OF MESSAGE--